

nVIDIA Series

(RIVA TNT/TNT2/TNT2 M64/TNT2 Ultra and VANTA)

FCC ID : ICUVGA-GW905A

Multimedia VGA Controller

Installation Guide

Version 3.0

06/99

Trademark Acknowledgments

Microsoft is a trademark of Microsoft Corporation.

All other brand and product names are trademarks or registered trademarks of their respective companies.



MMMVP005-30E6RN

FCC Notice

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

Notice:

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection. This equipment generates, uses and can radiated radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Shielded interface cables (except S-Video data cable) must be used in order to comply with emission limits.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Warning:

Shielded interface cables must be used in order to comply with emission limits.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

CSA Notice:

This digital apparatus does not exceed the Class B limits for radio noise emissions from digital apparatus set out in the Radio Interference Regulations of the Canadian Department of Communications.

Table of Contents

<i>Chapter 1 Overview</i>	<i>1</i>
<i>Chapter 2 Hardware Installation</i>	<i>3</i>
<i>Chapter 3 Software Installation.....</i>	<i>5</i>
<i>Chapter 4 Display Properties for Windows.....</i>	<i>6</i>
<i>Chapter 5 TV Output for Windows (Option).....</i>	<i>9</i>
<i>Chapter 6 Expertool for Windows</i>	<i>10</i>
<i>Chapter 7 Technical Information.....</i>	<i>13</i>
<i>Chapter 8 Trouble Shooting</i>	<i>15</i>