


REVISION HISTORY			
REV	DESCRIPTION	DATE	APPROVED
P6	RELEASE DWG PER PCO	9/20/02	J.ANGCANAN







8 THE REST OF THE ASSEMBLY PART NUMBER AND REVISION LETTER SHOULD BE STAMPED WITH INDELIBLE INK IN THE SILKSCREENED BLOCK NEXT TO THE 20-. AFTER STAMPING, THE PART NUMBER AND REVISION SHOULD MATCH THIS DOCUMENT.

7 INSTALL LASER BRACE ON COMPONENT SIDE OF PCB AS SHOWN. INSTALL LASER ASSY ON TOP OF BRACE, SOLDERING 2 LEADS TO LASER MOUNTING HOLES. LASER ASSY SHOULD BE FULLY SEATED ON BRACE. TRIM EXCESS LEADS FLUSH TO THE PCB.

6 MOUNT RESONATOR ON COMPONENT SIDE SO THAT IT LAYS PARALLEL TO THE PCB AND IS ORIENTED AS SHOWN.

5 THIS ASSEMBLY CONTAINS ESD SENSITIVE COMPONENTS. THEREFORE, ESD PRECAUTIONARY MEASURES SHOULD BE TAKEN IN PRODUCTION, TEST, AND HANDLING OF THIS ASSY.

4. ASSEMBLY MUST MEET ANSI/ IPC-A-610C OR BETTER.

3 VERIFY POLARITY OF FOLLOWING COMPONENTS: C1,C8,D1,Q3, U1-U3


2. REMOVE ALL BURRS FROM THE EDGE OF THE PCB AFTER ASSEMBLY AND BREAK AWAY (FROM ARRAY). ALL EDGES SHOULD BE SMOOTH.

1. SEE SEPARATE BILL OF MATERIALS.

NOTES : UNLESS OTHERWISE SPECIFIED.

APPROVALS	DATE	INTERLINK ELECTRONICS, 546 Flynn Road, Camarillo, CA 93012
J.ANGCANAN	8/30/02	TITLE: PCBA,Tx,IE,Celica
SIZE: C	DWG NO: 20-89778	REV: P6
SCALE: NONE	DO NOT SCALE DRAWING	SHEET 1 OF 2

REVISION HISTORY	
REV	DESCRIPTION
P6	SEE SHEET 1



SIZE		DWG NO.	REV.
C		20-89778	P6
SCALE NONE	DO NOT SCALE DRAWING	SHEET 2 OF 2	