


EMC TEST SETUP PHOTOS




EMC Report #23482 AC Line - Part 15



EMC Report #23482 Part 15, PC Peripheral



EMC Report #23482Antenna - Substitution



EMC Report #23482 Tx Radiated