





11AX20MIMO_Ant1_6515



Date: 20.JUN.2022 22:41:15


11AX20MIMO_Ant2_6515



Date: 20.JUN.2022 22:42:23




11AX20MIMO_Ant1_6535



Date: 20.JUN.2022 22:43:38


11AX20MIMO_Ant2_6535




Date: 20.JUN.2022 22:44:47



11AX20MIMO_Ant1_6695




11AX20MIMO_Ant2_6695






11AX20MIMO_Ant1_6855



Date: 20.JUN.2022 22:48:25


11AX20MIMO_Ant2_6855



Date: 20.JUN.2022 22:49:33




11AX20MIMO_Ant1_6875



Date: 20.JUN.2022 22:50:45


11AX20MIMO_Ant2_6875



Date: 20.JUN.2022 22:51:56




11AX20MIMO_Ant1_6895



Date: 20.JUN.2022 22:54:19


11AX20MIMO_Ant2_6895



Date: 20.JUN.2022 22:55:28




11AX20MIMO_Ant1_6995



Date: 20.JUN.2022 22:57:08


11AX20MIMO_Ant2_6995




Date: 20.JUN.2022 22:58:19



11AX20MIMO_Ant1_7095




11AX20MIMO_Ant2_7095






11AX40MIMO_Ant1_5965



Date: 20.JUN.2022 23:02:11


11AX40MIMO_Ant2_5965



Date: 20.JUN.2022 23:03:21




11AX40MIMO_Ant1_6165



Date: 20 JUN 2022 23:04:36


11AX40MIMO_Ant2_6165



Date: 20 JUN 2022 23:05:44




11AX40MIMO_Ant1_6405



Date: 20.JUN.2022 23:08:48


11AX40MIMO_Ant2_6405



Date: 20.JUN.2022 23:09:57




11AX40MIMO_Ant1_6445



Date: 20.JUN.2022 23:11:55


11AX40MIMO_Ant2_6445



Date: 20.JUN.2022 23:13:01




11AX40MIMO_Ant1_6485



Date: 20.JUN.2022 23:18:12


11AX40MIMO_Ant2_6485



Date: 20.JUN.2022 23:16:39




11AX40MIMO_Ant1_6525



Date: 20.JUN.2022 23:19:22


11AX40MIMO_Ant2_6525



Date: 20.JUN.2022 23:20:32




11AX40MIMO_Ant1_6565



Date: 20.JUN.2022 23:21:40


11AX40MIMO_Ant2_6565



Date: 20.JUN.2022 23:22:49




11AX40MIMO_Ant1_6685



Date: 20.JUN.2022 23:23:59


11AX40MIMO_Ant2_6685



Date: 20.JUN.2022 23:25:07




11AX40MIMO_Ant1_6845



Date: 20.JUN.2022 23:26:19


11AX40MIMO_Ant2_6845




Date: 20.JUN.2022 23:27:26



11AX40MIMO_Ant1_6885




11AX40MIMO_Ant2_6885






11AX40MIMO_Ant1_6925




11AX40MIMO_Ant2_6925






11AX40MIMO_Ant1_6965



Date: 20.JUN.2022 23:33:15


11AX40MIMO_Ant2_6965




Date: 20.JUN.2022 23:34:22



11AX40MIMO_Ant1_7085




11AX40MIMO_Ant2_7085






11AX80MIMO_Ant1_5985



Date: 20.JUN.2022 23:37:53


11AX80MIMO_Ant2_5985



Date: 20.JUN.2022 23:39:02




11AX80MIMO_Ant1_6145



Date: 20.JUN.2022 23:40:12


11AX80MIMO_Ant2_6145



Date: 20.JUN.2022 23:41:19




11AX80MIMO_Ant1_6385



Date: 20.JUN.2022 23:42:29


11AX80MIMO_Ant2_6385



Date: 20.JUN.2022 23:43:37



11AX80MIMO_Ant1_6465



11AX80MIMO_Ant2_6465

