





11A-CDD_Ant1_5745



Date: 11.JUN.2022 05:40:19


11A-CDD_Ant2_5745



Date: 11.JUN.2022 05:41:16




11A-CDD_Ant1_5785



Date: 11.JUN.2022 05:43:37


11A-CDD_Ant2_5785



Date: 11.JUN.2022 05:44:37




11A-CDD_Ant1_5825



Date: 11.JUN.2022 05:45:56


11A-CDD_Ant2_5825




Date: 11.JUN.2022 05:46:55



11AX20MIMO_Ant1_5180




11AX20MIMO_Ant2_5180






11AX20MIMO_Ant1_5220




11AX20MIMO_Ant2_5220






11AX20MIMO_Ant1_5240




11AX20MIMO_Ant2_5240






11AX20MIMO_Ant1_5260




11AX20MIMO_Ant2_5260






11AX20MIMO_Ant1_5300




11AX20MIMO_Ant2_5300






11AX20MIMO_Ant1_5320



Date: 11.JUN.2022 06:45:09


11AX20MIMO_Ant2_5320




Date: 11.JUN.2022 06:46:07



11AX20MIMO_Ant1_5500




11AX20MIMO_Ant2_5500






11AX20MIMO_Ant1_5580



Date: 11.JUN.2022 06:50:13


11AX20MIMO_Ant2_5580




Date: 11.JUN.2022 06:51:12



11AX20MIMO_Ant1_5700




11AX20MIMO_Ant2_5700






11AX20MIMO_Ant1_5720



Date: 11.JUN.2022 08:19:41


11AX20MIMO_Ant2_5720




Date: 11.JUN.2022 08:20:52



11AX20MIMO_Ant1_5745




11AX20MIMO_Ant2_5745






11AX20MIMO_Ant1_5785



Date: 11.JUN.2022 06:59:35


11AX20MIMO_Ant2_5785



Date: 11.JUN.2022 07:00:41




11AX20MIMO_Ant1_5825



Date: 11.JUN.2022 07:02:13


11AX20MIMO_Ant2_5825




Date: 11.JUN.2022 07:03:11



11AX40MIMO_Ant1_5190




11AX40MIMO_Ant2_5190






11AX40MIMO_Ant1_5230



Date: 11.JUN.2022 07:07:07


11AX40MIMO_Ant2_5230



Date: 11.JUN.2022 07:08:13




11AX40MIMO_Ant1_5270



Date: 11.JUN.2022 07:09:41


11AX40MIMO_Ant2_5270



Date: 11.JUN.2022 07:10:41




11AX40MIMO_Ant1_5310



Date: 11.JUN.2022 07:12:01


11AX40MIMO_Ant2_5310



Date: 11.JUN.2022 07:13:06




11AX40MIMO_Ant1_5510



Date: 11.JUN.2022 07:14:36


11AX40MIMO_Ant2_5510




Date: 11.JUN.2022 07:15:33



11AX40MIMO_Ant1_5550




11AX40MIMO_Ant2_5550






11AX40MIMO_Ant1_5670



Date: 11.JUN.2022 07:20:06


11AX40MIMO_Ant2_5670



Date: 11.JUN.2022 07:21:04




11AX40MIMO_Ant1_5710



Date: 11.JUN.2022 08:22:35


11AX40MIMO_Ant2_5710



Date: 11.JUN.2022 08:23:47




11AX40MIMO_Ant1_5755



Date: 11.JUN.2022 07:22:21


11AX40MIMO_Ant2_5755



Date: 11.JUN.2022 07:23:26




11AX40MIMO_Ant1_5795



Date: 11.JUN.2022 07:25:03


11AX40MIMO_Ant2_5795



Date: 11.JUN.2022 07:26:00




11AX80MIMO_Ant1_5210



Date: 11.JUN.2022 07:27:57


11AX80MIMO_Ant2_5210




Date: 11.JUN.2022 07:29:03



11AX80MIMO_Ant1_5290




11AX80MIMO_Ant2_5290






11AX80MIMO_Ant1_5530




11AX80MIMO_Ant2_5530






11AX80MIMO_Ant1_5610



Date: 11.JUN.2022 07:35:32


11AX80MIMO_Ant2_5610



Date: 11.JUN.2022 07:36:28




11AX80MIMO_Ant1_5690



Date: 11.JUN.2022 08:25:33


11AX80MIMO_Ant2_5690




Date: 11.JUN.2022 08:26:41



11AX80MIMO_Ant1_5775




11AX80MIMO_Ant2_5775






11AX160MIMO_Ant1_5250



Date: 9.JUL.2022 09:52:15


11AX160MIMO_Ant2_5250



Date: 9.JUL.2022 09:53:08




11AX160MIMO_Ant1_5570



Date: 9.JUL.2022 09:54:14

11AX160MIMO_Ant2_5570



Date: 9.JUL.2022 09:55:07