








11AX20MIMO_Ant5_6855



Date: 22.DEC.2022 20:08:06


11AX20MIMO_Ant4_6855




Date: 22.DEC.2022 20:10:06



11AX20MIMO_Ant5_6875




11AX20MIMO_Ant4_6875






11AX20MIMO_Ant5_6895




11AX20MIMO_Ant4_6895






11AX20MIMO_Ant5_6995




11AX20MIMO_Ant4_6995








11AX20MIMO_Ant5_7095




11AX20MIMO_Ant4_7095













11AX40MIMO_Ant5_6405




11AX40MIMO_Ant4_6405








11AX40MIMO_Ant5_6445





11AX40MIMO_Ant4_6445















11AX40MIMO_Ant5_6845



Date: 22.DEC.2022 21:09:26


11AX40MIMO_Ant4_6845



Date: 22.DEC.2022 21:11:20




11AX40MIMO_Ant5_6885



Date: 22.DEC.2022 21:13:36


11AX40MIMO_Ant4_6885




Date: 22.DEC.2022 21:15:39





11AX40MIMO_Ant5_6925



11AX40MIMO_Ant4_6925











11AX80MIMO_Ant5_5985



Date: 22.DEC.2022 21:42:23


11AX80MIMO_Ant4_5985



Date: 22.DEC.2022 21:44:24




11AX80MIMO_Ant5_6145





Date: 22.DEC.2022 21:46:44


11AX80MIMO_Ant4_6145





Date: 22.DEC.2022 21:46:47























11AX80MIMO_Ant5_7025



11AX80MIMO_Ant4_7025

