










11AX20MIMO_Ant5_6175



11AX20MIMO_Ant4_6175











11AX20MIMO_Ant5_6475




11AX20MIMO_Ant4_6475






11AX20MIMO_Ant5_6515




11AX20MIMO_Ant4_6515






11AX20MIMO_Ant5_6535




11AX20MIMO_Ant4_6535






11AX20MIMO_Ant5_6695




11AX20MIMO_Ant4_6695







11AX20MIMO_Ant5_6855




11AX20MIMO_Ant4_6855










11AX20MIMO_Ant5_6895



11AX20MIMO_Ant4_6895











11AX20MIMO_Ant5_7115



Date: 22.DEC.2022 20:31:19


11AX20MIMO_Ant4_7115




Date: 22.DEC.2022 20:33:20



11AX40MIMO_Ant5_5965




11AX40MIMO_Ant4_5965






11AX40MIMO_Ant5_6165




11AX40MIMO_Ant4_6165






11AX40MIMO_Ant5_6405




11AX40MIMO_Ant4_6405






11AX40MIMO_Ant5_6445




11AX40MIMO_Ant4_6445








11AX40MIMO_Ant5_6485





11AX40MIMO_Ant4_6485















11AX40MIMO_Ant5_6885




11AX40MIMO_Ant4_6885






11AX40MIMO_Ant5_6925




11AX40MIMO_Ant4_6925





11AX40MIMO_Ant5_6965



11AX40MIMO_Ant4_6965

