




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 176 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 177 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 178 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 179 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 180 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 181 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 182 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 183 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 184 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 185 of 685




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
 Rev.: 01
 Page: 186 of 685

802.11ax(HEW40)_LCH_5965MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_LCH_5965MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 187 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 188 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 189 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 190 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 191 of 685




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
 Rev.: 01
 Page: 192 of 685

802.11ax(HEW80)_MCH_6145MHz_SU_/_Ant4_NTNV




802.11ax(HEW80)_MCH_6145MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 193 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 194 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 195 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 196 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 197 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 198 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 199 of 685

4.2.2 E.I.R.PSD







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 200 of 685

802.11a_LCH_5955MHz_MIMO_NTNV




802.11a_MCH_6175MHz_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 201 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 202 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 203 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 204 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 205 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 206 of 685








SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 208 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 209 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 210 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 211 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 212 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 213 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 214 of 685



802.11ax(HEW20)_MCH_6175MHz_SU / _MIMO_NTNV



802.11ax(HEW20)_HCH_6415MHz_RU26 / _Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 216 of 685

802.11ax(HEW20)_HCH_6415MHz_RU26 / Ant4_NTNV




802.11ax(HEW20)_HCH_6415MHz_RU26 / MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 217 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 218 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 219 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 220 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 221 of 685







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 222 of 685

802.11ax(HEW40)_LCH_5965MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_LCH_5965MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 223 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 224 of 685




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
 Rev.: 01
 Page: 225 of 685

802.11ax(HEW40)_HCH_6405MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_HCH_6405MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 226 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 227 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 228 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 229 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 230 of 685



802.11ax(HEW160)_LCH_6025MHz_SU_/_Ant4_NTNV




802.11ax(HEW160)_LCH_6025MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 232 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 233 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 234 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 235 of 685


4.2.3 PSD





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 236 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 237 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 238 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 239 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 240 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 241 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 242 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 243 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 244 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 245 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 246 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 247 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 248 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 249 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 250 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 251 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 252 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 253 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 254 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 255 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 256 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 257 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 258 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 259 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 260 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 261 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 262 of 685


4.2.4 E.I.R.PSD





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 263 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 264 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 265 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 266 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 267 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 268 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 269 of 685



SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
 Rev.: 01
 Page: 270 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 271 of 685



802.11ax(HEW20)_LCH_6435MHz_SU_/_MIMO_NTNV




802.11ax(HEW20)_MCH_6475MHz_RU26_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 273 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 274 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 275 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 276 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 277 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 278 of 685




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
 Rev.: 01
 Page: 279 of 685

802.11ax(HEW20)_HCH_6515MHz_RU26 / Ant4_NTNV




802.11ax(HEW20)_HCH_6515MHz_RU26 / MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 280 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 281 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 282 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 283 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 284 of 685







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 285 of 685

802.11ax(HEW40)_LCH_6445MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_LCH_6445MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 286 of 685




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
 Rev.: 01
 Page: 287 of 685

802.11ax(HEW40)_MCH_6485MHz_SU / _MIMO_NTNV




802.11ax(HEW80)_LCH_6465MHz_SU / _Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 288 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 289 of 685

4.2.5 PSD







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 290 of 685

802.11a_LCH_6535MHz_MIMO_NTNV




802.11a_MCH_6695MHz_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 291 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 292 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 293 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 294 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 295 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 296 of 685








SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 298 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 299 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 300 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 301 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 302 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 303 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 304 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 305 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 306 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 307 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 308 of 685




SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
 Rev.: 01
 Page: 309 of 685

802.11ax(HEW20)_HCH_6855MHz_RU106 / Ant4_NTNV




802.11ax(HEW20)_HCH_6855MHz_RU106 / MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 310 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 311 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 312 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 313 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 314 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 315 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 316 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 317 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 318 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 319 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 320 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 321 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 322 of 685

4.2.6 E.I.R.PSD







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 323 of 685

802.11a_LCH_6535MHz_MIMO_NTNV




802.11a_MCH_6695MHz_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 324 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 325 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 326 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 327 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 328 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 329 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 330 of 685







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 331 of 685

802.11ax(HEW20)_LCH_6535MHz_SU_/_Ant5_NTNV




802.11ax(HEW20)_LCH_6535MHz_SU_/_Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 332 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 333 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 334 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 335 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 336 of 685







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 337 of 685

802.11ax(HEW20)_MCH_6695MHz_SU_/_Ant5_NTNV




802.11ax(HEW20)_MCH_6695MHz_SU_/_Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 338 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 339 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 340 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 341 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 342 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250200006307
Rev.: 01
Page: 343 of 685





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 344 of 685






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250200006307
Rev.: 01
Page: 345 of 685

802.11ax(HEW40)_LCH_6565MHz_SU_/_Ant4_NTNV



802.11ax(HEW40)_LCH_6565MHz_SU_/_MIMO_NTNV

