





Plot on 6855 MHz




01:06:29 AM 09/08/2026

Plot on 6875 MHz




01:09:31 AM 09/08/2026

Plot on 6895 MHz



01:14:18 AM 09/08/2026


Plot on 6995 MHz



01:18:11 AM 09/08/2026



Plot on 7095 MHz







EUT Mode

802.11ax HE20 26RU0


## Plot on 5955 MHz



## Plot on 6435 MHz




## Plot on 6535 MHz





|          |                     |
|----------|---------------------|
| EUT Mode | 802.11ax HE20 26RU8 |
|----------|---------------------|

Plot on 7095 MHz






EUT Mode


802.11ax HE20 52RU37

## Plot on 5955 MHz




05:32:52 PM 09/12/2026

## Plot on 6435 MHz



06:29:03 PM 09/12/2026

## Plot on 6535 MHz




07:10:45 PM 09/12/2026



|          |                      |
|----------|----------------------|
| EUT Mode | 802.11ax HE20 52RU40 |
|----------|----------------------|

Plot on 7095 MHz






EUT Mode


802.11ax HE20 106RU53

## Plot on 5955 MHz




05:47:22 PM 09/12/2026

## Plot on 6435 MHz



06:52:06 PM 09/12/2026

## Plot on 6535 MHz




07:17:18 PM 09/12/2026



EUT Mode

802.11ax HE20 106RU54

Plot on 7095 MHz






EUT Mode


802.11ax HE40 FullRU

Plot on 5965 MHz




11:33:11 PM 09/07/2026

Plot on 6205 MHz




11:39:29 PM 09/07/2026

Plot on 6405 MHz



11:42:02 PM 09/07/2026


Plot on 6445 MHz



11:44:24 PM 09/07/2026




Plot on 6485 MHz




11:48:25 PM 09/07/2026

Plot on 6565 MHz




11:55:58 PM 09/07/2026

Plot on 6685 MHz



11:59:13 PM 09/07/2026


Plot on 6845 MHz



12:02:01 AM 09/08/2026




## Plot on 6885 MHz




12:04:21 AM 09/08/2026

## Plot on 6925 MHz




12:08:18 AM 09/08/2026

## Plot on 7005 MHz



12:12:26 AM 09/08/2026


## Plot on 7085 MHz



12:15:29 AM 09/08/2026



Plot on 6525 MHz






EUT Mode


802.11ax HE80 FullIRU

Plot on 5985 MHz




01:00:45 AM 09/09/2026

Plot on 6225 MHz




01:18:37 AM 09/09/2026

Plot on 6385 MHz



01:23:24 AM 09/09/2026


Plot on 6465 MHz



01:27:21 AM 09/09/2026




## Plot on 6625 MHz




01:37:43 AM 09/09/2026

## Plot on 6705 MHz




07:27:34 PM 09/09/2026

## Plot on 6785 MHz



07:32:31 PM 09/09/2026


## Plot on 6865 MHz



07:42:09 PM 09/09/2026




## Plot on 6945 MHz




07:47:42 PM 09/09/2026

## Plot on 7025 MHz



07:53:47 PM 09/09/2026

## Plot on 6545 MHz




01:32:34 AM 09/09/2026



EUT Mode


802.11ax HE160 FullIRU

Plot on 6025 MHz




12:11:41 AM 09/09/2026

Plot on 6185 MHz




12:14:04 AM 09/09/2026

Plot on 6345 MHz



12:19:16 AM 09/09/2026


Plot on 6665 MHz



12:35:22 AM 09/09/2026




## Plot on 6825 MHz




12:39:32 AM 09/09/2026

## Plot on 6985 MHz



12:44:31 AM 09/09/2026

## Plot on 6505 MHz




12:31:18 AM 09/09/2026



EUT Mode


802.11be EHT20 FullIRU

Plot on 5955 MHz




08:24:25 PM 09/06/2026

Plot on 6195 MHz




09:42:29 PM 09/06/2026

Plot on 6415 MHz



10:15:13 PM 09/06/2026


Plot on 6435 MHz



10:32:34 PM 09/06/2026




Plot on 6475 MHz




10:45:56 PM 09/06/2026

Plot on 6515 MHz




10:54:56 PM 09/06/2026

Plot on 6535 MHz



11:07:36 PM 09/06/2026

Plot on 6695 MHz



11:16:53 PM 09/06/2026