


EMC TEST SETUP PHOTOS




EMC Report #23574 AC Line - Part 15




EMC Report #23574 Part 15, PC Peripheral front view




EMC Report #23574 Part 15, PC Peripheral rear view



EMC Report #23574Antenna - Substitution



EMC Report #23574 Tx Radiated front view



EMC Report #23574 Tx Radiated rear view