



3. Internal Photograph of EUT

Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7



Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7






Brand Name: Motorola / Model Name: XT1955-7



Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7







Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7



Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7







Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7



Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7






Brand Name: Motorola / Model Name: XT1955-7




Page Number : 45 of 67
Report Issued Date : Nov. 09, 2018
Report Version : Rev. 01



Brand Name: Motorola / Model Name: XT1955-7




Brand Name: Motorola / Model Name: XT1955-7






Brand Name: Motorola / Model Name: XT1955-7



Brand Name: Motorola / Model Name: XT1955-7





Brand Name: Motorola / Model Name: XT1955-7

