

13 TEST SETUP PHOTOGRAPHS



Picture 1: Spurious emission measurement setup



Picture 2: Spurious emission and field strength measurement setup

EUT orientations

Picture 3: Pos 1



Picture 4: Pos 2



Picture 5: Pos 3