

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT


REPORT NO. : F852204

6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

FRONT VIEW



REAR VIEW



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F852204

5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

FRONT VIEW



REAR VIEW



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F852204

SIDE VIEW



APPLICANT : NATIONAL DATACOMM CORPORATION

EQUIPMENT : SOHO ware HUB

F C C I D : IOUND4205S01

ISSUED DATE : JUN. 08, 1998

PAGE NUMBER : 15 OF22