






Garmin International, Inc.
MODEL: IQue M5
Test #: 040715 FCCID#: IPH-00793
Test to: FCC Parts 2 and 15.247



Page 1
IPH00793IntPhot.doc 8/24/2004



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: IQue M5
Test #: 040715
Test to: FCC Parts 2 and 15.247

FCCID#: IPH-00793




ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: IQue M5
Test #: 040715 FCCID#: IPH-00793
Test to: FCC Parts 2 and 15.247



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: IQue M5
Test #: 040715 FCCID#: IPH-00793
Test to: FCC Parts 2 and 15.247



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: IQue M5
Test #: 040715
Test to: FCC Parts 2 and 15.247

FCCID#: IPH-00793

Page 5 of 5

IPH00793IntPhot.doc 8/24/2004