





Internal photographs of GMR 40X.
Modulator Top and Bottom



IF Board 1 Top and Bottom





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 2 of 9

IF Board 2 Top and Bottom





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 3 of 9

Rotation detector top and bottom



Main Board top and bottom





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 5 of 9

Voltage Converter top and bottom





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 6 of 9



Down Converter top and bottom



Voltage converter top and bottom



Motor control top and bottom



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: GMR40X
Test #: 060406
Test to: FCC Parts 2 and 80

IC: 1792A-00991
FCCID#: IPH-00991
Page 9 of 9