



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc. SN's: CE/FCC unit1, CE/FCC unit2
Model: A03198
Test #: 170817
Test to: CFR47 15C, RSS-247, RSS-210
File: A03198 Short Term Conf TSup

FCC ID: IPH-03198
IC: 1792A-03198
Date: October 16, 2017
Page 1 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc. SN's: CE/FCC unit1, CE/FCC unit2
Model: A03198
Test #: 170817
Test to: CFR47 15C, RSS-247, RSS-210
File: A03198 Short Term Conf TSup

FCC ID: IPH-03198
IC: 1792A-03198
Date: October 16, 2017
Page 2 of 3



Rogers Labs, Inc.
 4405 West 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Garmin International, Inc. SN's: CE/FCC unit1, CE/FCC unit2
 Model: A03198
 Test #: 170817
 Test to: CFR47 15C, RSS-247, RSS-210
 File: A03198 Short Term Conf TSup

FCC ID: IPH-03198
 IC: 1792A-03198
 Date: October 16, 2017
 Page 3 of 3