

SAR Test Setup Photos



Test Position Back 0 mm Gap



Front of Device



Back of Device