

Appendix C – SAR Test Setup Photos



Test Position Back 0 mm Gap



Test Position Front 0 mm Gap



Test Position Left 0 mm Gap



Test Position Right 0 mm Gap



Test Position Top 0 mm Gap




Test Position Bottom 0 mm Gap



Front of Device



Back of Device



Duty Cycle of Transmitter