


Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04797, B04797
Test: 230721A
Test to: 47CFR 15C, RSS-210, RSS-247
File: 04797 Short Term Conf TSup

FCC ID: IPH-04797
IC: 1792A-04797
SN's: 3449473321, 3449472678
Date: October 9, 2023
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04797, B04797
Test: 230721A
Test to: 47CFR 15C, RSS-210, RSS-247
File: 04797 Short Term Conf TSup


FCC ID: IPH-04797
IC: 1792A-04797
SN's: 3449473321, 3449472678
Date: October 9, 2023
Page 2 of 4



Rogers Labs, Inc.
 4405 West 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Garmin International, Inc.
 HVIN: A04797, B04797
 Test: 230721A
 Test to: 47CFR 15C, RSS-210, RSS-247
 File: 04797 Short Term Conf TSup

FCC ID: IPH-04797
 IC: 1792A-04797
 SN's: 3449473321, 3449472678
 Date: October 9, 2023
 Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Garmin International, Inc.
HVIN: A04797, B04797
Test: 230721A
Test to: 47CFR 15C, RSS-210, RSS-247
File: 04797 Short Term Conf TSup

FCC ID: IPH-04797
IC: 1792A-04797
SN's: 3449473321, 3449472678
Date: October 9, 2023
Page 4 of 4