

EXHIBIT 15 – PHOTOS – EMC AND SAR SETUP

Figure E15.1 – Setup, Antenna Port Conducted Measurements




Figure E15.2 – Setup, Radiated Measurements Below 30MHz




Figure E15.3 – Setup, Radiated Measurements 30 – 1000MHz




Figure E15.4 – Setup, Radiated Rx Measurements 1 – 18GHzHz



Figure E15.5 – Setup, Radiated Tx Measurements 1 – 18GHz



Figure E15.6 – Setup, Radiated Tx Measurements 18 – 26GHz



Figure E15.7 – Setup, Line Conducted Measurements



Figure E15.8 – Setup, Frequency Stability Measurements




Figure E15.9 – Setup, Frequency Stability Measurements



Figure E15.10 – Photo – Setup: Extremity, DUT Back – Silicone Band (E21)




Figure E15.11 – Photo Close Up – Setup: Extremity, DUT Back 0mm– Silicone Band (E21)



Figure E15.12 – Photo – Setup: Extremity, DUT Back 0mm- Metal Band (E22)




Figure E15.13 – Photo Close Up – Setup: Extremity, DUT Back 0mm- Metal Band (E22)



Figure E15.14 – Photo – Setup: Face, DUT Front 10mm – Silicone Band (F23)

