

EXHIBIT 15 – PHOTOS – EMC AND SAR SETUP

Figure E15.1 – Setup, Conducted Measurements




Figure E15.2 – Setup, Radiated Measurements, 9kHz – 30MHz



Figure E15.3 – Setup, Radiated Measurements, 30 – 1000MHz



Figure E15.4 – Setup, Radiated Rx Measurements, 1 – 18GHz



Figure E15.5 – Setup, Radiated Tx Measurements, 1 – 18GHz



Figure E15.6 – Setup, Radiated Tx Measurements, 18 – 26GHz



Figure E15.7 – Setup, Frequency Stability




Figure E15.8 – Setup, Frequency Stability



Figure E15.9 – Setup, Line Conducted Measurements



Figure E15.10 – Photo – Setup: Extremity, DUT Back 0mm- Silicone Band



Figure E15.11 – Photo – Setup: Extremity, DUT Back 0mm- Silicone Band - close



Figure E15.12 – Photo – Setup: Face, DUT Front 10mm – Silicone Band




Figure E15.13 – Photo – Setup: Face, DUT Front 10mm – Silicone Band – close

