


Internal photographs of IVQFAL-HR equipment





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Kustom Signals Inc.
MODEL: Falcon/HR
Test #: 061107
Test to: FCC Parts 2 and 90

FCCID#: IVQFAL-HR
S/N: FH01001

Page 1 of 3
IVQFALL-HR Internal Photos 11/10/2006





ROGERS LABS, INC.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214

Kustom Signals Inc.
 MODEL: Falcon/HR
 Test #: 061107
 Test to: FCC Parts 2 and 90

FCCID#: IVQFAL-HR
 S/N:FH01001

Page 2 of 3

IVQFALL-HR Internal Photos 11/10/2006



ROGERS LABS, INC.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214

Kustom Signals Inc.
 MODEL: Falcon/HR
 Test #: 061107
 Test to: FCC Parts 2 and 90

FCCID#: IVQFAL-HR
 S/N: FH01001

Page 3 of 3
 IVQFALL-HR Internal Photos 11/10/2006