

08 November 2022

Compliance Statement in Car Manual / FCC ID: IYZCD1

Dear Sirs,

The product is a wireless seat buckle sensor

The product will be provided to our customer FORD Motor Company before they will be placed into the market.


Hereby we assure that the following caution statement as per CFR 47, Part 15, § 15.21 will be included in the owner's manual of the cars:

1. The title "CAUTION TO USERS" or "FCC Warning:" "NOTE:" or relevant title and
2. "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

In addition our client also assures that the following statement will be included in the manual as per CFR 47, Part 15, § 15.19 (a) (3).

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) *this device may not cause harmful interference, and*
- (2) *this device must accept any interference received, including interference that may cause undesired operation.*

ppa. 

Gerd Villing
Vice President Research & Development
+49 (0) 7424-99-1747
Gerd.Villing@Marquardt.com

08 November 2022

Compliance Statement in User Manual / IC: 2701A-CD1

Dear Sirs,

The product will be provided to our customer FORD Motor Company before they will be placed into the market.

Hereby we assure that the following caution statement as requested per RSS Regulation will be included in the owner's manual of the cars:

This device complies with Industry Canada's licence-exempt RSSs. Operation is subject to the following two conditions:

- (1) This device may not cause interference; and*
- (2) This device must accept any interference, including interference that may cause undesired operation of the device.*

Le present appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes:

- (1) l'appareil ne doit pas produire de brouillage;*
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement."*



ppa
Gerd Villing
Vice-President Research & Development
+49 (0) 7424-99-1747
Gerd.Villing@Marquardt.com