

Certification Exhibit

Test Photos

Marquardt GmbH
NH1

In accordance with:
FCC Part 15 Subpart C §15.225
ISED RSS-210 Issue 10, December 2019,
Amendment 2020

FCC ID: IYZNH1
IC: 2701A-NH1

Prepared for: Marquardt GmbH
Schloss-Str. 16
78604 Rietheim-Weilheim, Germany



America

**Add value.
Inspire trust.**

COMMERCIAL-IN-CONFIDENCE

Document Number: NC72193137.3 | Issue: 1

SIGNATURE

A handwritten signature in black ink, appearing to read "Brad Reasoner", written over a white background.

NAME	JOB TITLE	RESPONSIBLE FOR	ISSUE DATE
Brad Reasoner	EMC Technical Lead	Authorized Signatory	16 October 2023

Signatures in this approval box have checked this document in line with the requirements of TÜV SÜD America, Inc. document control rules.

FCC Accreditation
Designation Number US1148 New Brighton, MN Test
Laboratory

Innovation, Science, and Economic Development Canada
Accreditation
Site Number 4512A New Brighton, MN Test Laboratory



Contents

1.1	EUT Photo	3
1.2	Fields Strength within the bands 13.110 MHz – 14.010 MHz	4
1.3	Fields Strength outside the bands 13.110 MHz – 14.010 MHz	5
1.4	Frequency Tolerance	7

1.1 EUT Photo



Photo 1.1-1 – EUT Photo

1.2 Fields Strength within the bands 13.110 MHz – 14.010 MHz




Photo 1.2-1 – 13.110MHz – 14.01MHz In Band Measurement – Test Setup – Rear Side



Photo 1.2-2 – 13.110MHz – 14.01MHz In Band Measurement – Test Setup – Rear Side

TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com

1.3 Fields Strength outside the bands 13.110 MHz – 14.010 MHz




Photo 1.3-1 – 13.110MHz – 14.01MHz In Band Measurement – Test Setup – Rear Side



Photo 1.3-2 – 13.110MHz – 14.01MHz In Band Measurement – Test Setup – Rear Side

TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com



Photo 1.3-3 – RE Spurious Emissions 30-1000 MHz – Front Side




Photo 1.3-4 – RE Spurious Emissions 30-1000 MHz – Back Side

TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com

1.4 Frequency Tolerance




Photo 1.4-1 – Frequency Tolerance – Setup 1



Photo 1.4-2 – Frequency Tolerance – Setup 2

TÜV SÜD America Inc
141 14th Street NW
New Brighton, MN 55112

Phone: 651-631-2487
www.tuv-sud-america.com