



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 14, 2005

RE: Rokonet Electronics Ltd.

FCC ID: JE4RK315DT

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The schematic provide are not of sufficient resolution. Please correct.
- 2) For documentation purposes of what is Certified, the FCC requires internal view of the module, even when this module is OEM'd. It still appears that additional circuitry exists inside the module that is not shown (i.e. back side of antenna board, etc.). Please provide.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.