

Annex 2 - Internal Photographs



Figure 1. Circuit Board Top with Connections

U.S. Tech Test Report:
FCC ID:
IC:
Report Number:
Issue Date:
Customer:
Model:

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X



Figure 2. Circuit Board Side 1

U.S. Tech Test Report:
FCC ID:
IC:
Report Number:
Issue Date:
Customer:
Model:

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X



Figure 3. Side 2, Heat Sink

U.S. Tech Test Report:
FCC ID:
IC:
Report Number:
Issue Date:
Customer:
Model:

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X




Figure 4. Side 2

U.S. Tech Test Report:
FCC ID:
IC:
Report Number:
Issue Date:
Customer:
Model:

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X



Figure 5. Side 2

U.S. Tech Test Report:
FCC ID:
IC:
Report Number:
Issue Date:
Customer:
Model:

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X




Figure 6. Bottom

U.S. Tech Test Report:
FCC ID:
IC:
Report Number:
Issue Date:
Customer:
Model:

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X




Figure 7. Power Transistors

FCC Part 95, IC RSS-236
JOFRS2025X
5855A-2025X
14-0096 & 14-0097
June 26, 2014
Radio Sound Inc.
RS2025X

