



This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions: (1)
This device must not cause harmful interference, and (2)
this device must accept any interference received,
including interference that may cause undesired operation.

DATE MFG
RECEIVED

WARNING

Use only batteries specified in marking. Use of a different battery will have a detrimental effect on detector operation.

When replacing batteries, remove all batteries, wait 30 seconds after removal before inserting new batteries. For proper operation use only 3 volt lithium battery Duracell DL123A, Sanyo CR123A or Panasonic CR123A.

Model 552ST
Self diagnostic photoelectric smoke detector
Sensitivity 1.5 to 2.1 sqft. Do not use where
power up time is seconds. Operating voltage 3.0
VDC. Heat up time 15 seconds. Rate
of rise > 15°F/min. Test by depressing test button twice a year.
Test weekly. Trouble by 155.15.
For service, return to Sanyo, 12345 SW Lenoir
Dr., Tualatin, OR 97062. 1-800-648-7424
ISSUE NO. 80210.



LISTED



S1272


WARNING

Cannot be mounted and will not
operate without batteries installed.

US Pat. No. 5,646,074;
5,799,701; 5,821,866; 5,836,533







C3

J1

S2

D1

H1

C1

VX(M) VX(M)
5°C 85°C
942 N N

C2

S1

MADE IN USA

multiPolar

SI
HCF4049UBE
WK00J9944
CHINA

SENTROL®
14262D

C5

U1

10 µF 25V 10 µF 25V
VX(M) VX(M)

20

PC-A

