

LUTRON

ELECTRONICS CO., INC.

Lutron Electronics Co., Inc.
7200 Suter Road
Coopersburg, Pa 18036
21 October 2014

UL TCB
333 Pfingsten Rd.
Northbrook, IL 60062-2096

Subject: Class II changes to JPZ0107


Identifier: FCC ID: JPZ0107 (2014-06-30)
IC: 2851A-JPZ0107 (2014-07-01)

Equipment class: RF touch dimmer

Updates were made to provide better RF response that is less affected by installation characteristics with various faceplates that load the device antenna.


In the process, updates were also made in the RF Harmonic filter to improve the devices rejection performance with respect to harmonic frequencies. The overall output power of the device has not changed for the typical installation methods.

Submitted by:



Richard Camden
Director of Engineering RF Systems

Reviewed by:



Robert Spenhalski
Engineering Leader