

INTERTEK TESTING SERVICES - Menlo Park

Teledesign Radio Modem W/ 3474 Transceiver

Date of Test: 7/2&3/98 & 7/6-8/98

Appendix C - Block Diagram

See attached.

TS4000 Radio Modem Block Diagram and Clock Signal Distribution

