



January 3, 2005

To: Whom it may concern,

The datarate of the LT802 was not set during the compliance testing that was done at CCS. Later we determined that the radio operates in "Full Auto" mode when the datarate is not specified. Also, the default datarate in Full Auto mode is the highest datarate which turns out to have the highest output level and is the worst case.

The data in the LT802 report was taken at CCS when the LT802 was operating at the highest datarate and the highest output level.

Regards,
Steve Luzovich
VP of Engineering