

YAESU

YAESU MUSEN CO., LTD.

Tennozu Parkside Building

2-5-8 Higashi-Shinagawa, Shinagawa-ku, Tokyo 140-0002 Japan

Tel: 81-(0)3-6711-4121 · Fax: 81-(0)3-6711-4278

6 December 2017

Timco Engineering, Inc.
849 NW State Road 45
P.O. Box 370
Newberry, FL 32669

SUBJECT:

No ability to program / FCC ID: K6630623X30 and IC: 511B-30623X30 Model: HX40

To Whom It May Concern:

This device's transmit frequencies can be performed only by the manufacturer or authorized service/maintenance personnel, and the users has no ability to program frequencies.

Regards,

YAESU MUSEN CO., LTD.



Kouji Taguchi

Engineering Division / Quality Assurance