




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

26 INTERNAL PHOTOGRAPHS

VX-600U-3:


Top of PCB Board





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Bottom of PCB Board





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Top of PCB Board without VR/SW/Shield Case





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Bottom of PCB Board without VR/SW/Shield Case





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Component Side of SW-UNIT





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Solder Side of SW-UNIT





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Component Side of VR-UNIT





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Solder Side of VR-UNIT





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Inside Front of Chassis





360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Inside Back of Chassis

