

Honeywell

Aspire 350



Power



Fault

S.I.S



Honeywell | Aspire 350

Description SDU 350



CAG 38473
PNO 90405928-001R
SEQ 114

EMS Technologies Canada Ltd. TCCA#325-92
400 Maple Grove Rd. Kanata, ON. K2V 1B8

Modifications:

①②③④⑤⑥⑦⑧⑨⑩⑪⑫

THIS DEVICE HAS NOT BEEN AUTHORIZED
AS REQUIRED BY THE RULES OF THE
FEDERAL COMMUNICATIONS COMMISSION.
THIS DEVICE IS NOT, AND MAY NOT BE, OFFERED
FOR SALE OR LEASE, OR SOLD OR LEASED,
UNTIL AUTHORIZATION IS OBTAINED.

CAUTION:
THIS EQUIPMENT
REQUIRES FIELD
LOADABLE SOFTWARE
ENSURE CORRECT
SOFTWARE IS LOADED.
REFER TO AMM.

LBT1 IMEI #
300125062024190

LBT2 IMEI #
300125062020200

HCM IMEI #
300008030002040

CAUTION
CONTAINS PARTS AND ASSEMBLIES
SUSCEPTIBLE TO DAMAGE BY
ELECTROSTATIC DISCHARGE (ESD)



