



HH38WX-ST CIRCUIT DIAGRAM FOR COBRA ----- SHEETS 2 OF 2

TRANSISTOR MARK:
 1.KTC3880S:AQG
 2.XTC3875S:ALG
 3.KTA1504S:ASY
 4.KRA105S:PE
 5.KRC110S:MK
 6.KRC101S:NA

