

2002/12/11

Regarding this product, we modified the board outline and added some components such as U9022 and U9021 etc. These components were unused. About antenna, we moved its position of the solder but did not added extra antenna.

Sincerely,

*Jim Lin*

Jim Lin

Hardware Engineer