



American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

January 28, 2003

RE: D-Link Corporation

FCC ID: KA22002090030

I have a few comments on this Application.

- 1.) Please review Manual. I cannot find any references to how end users can limit their RF exposure. [See last page of Manual]
- 2.) Block diagram shows signal paths, but not frequencies of any oscillators per 2.1033(a)(5).
- 3.) Device appears larger than the palm of the hand. Therefore, two part label language of 15.19(a)(3) is required to appear on the device. If placement in the Manual is still desired, please justify.
- 4.) Three differing physical configurations of this device appear in the External Photographs. Please explain what the differences are, and explain how they are different. If the "nose" of any one card is shorter than the others it may place the antenna elements closer to the body. It would then be reasonable to expect this to create a greater SAR. Are we looking at the "worst case" configuration? Please justify your choice.
- 5.) Please review the DoC form. D-Link has a large presence in US. Therefore it is my belief that a US contact is available.

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.