

Operation of the 17TN RF Key Fob.

1 Lock

Standing within the vicinity of the vehicle, depress the 17TN button marked with a padlock symbol to lock the vehicle and set the vehicle immobiliser and alarm system.

2 Unlock

Standing within the vicinity of the vehicle depress the unmarked 17TN button to unlock the vehicle and disable the immobiliser and alarm.

3 Changing the battery

Using a suitable instrument carefully prise apart the two halves to the 17TN to expose the key fob battery in its metal retaining clip. A slot at the key ring end of the 17TN is provide to facilitate opening the unit.

Note that the + symbol on the 17TN battery retaining clip and the + symbol on the battery in the 17TN are both uppermost. Then push the battery out of its retaining clip using a blunt, non-conducting implement such as a matchstick.

Remove a new battery from its packaging and push it gently into the 17TN battery clip making sure that the positive (+) terminal of the battery is uppermost. Take special care to avoid handling the battery, as tests have shown that the perspiration from human fingers can create a conductive path that will shorten battery life. The recommended method of inserting a new battery is to push it out of its packaging directly into the 17TN clip using a blunt non-conductive implement.

To re-assemble the 17TN, align to two halves of the unit and press them together.

After battery replacement, the 17TN and the vehicle security system will have lost synchronisation. To re-synchronise the key and the vehicle, stand close to the vehicle and press either the lock or unlock button (but not both) four times over a period of two seconds.

6 'Learning' a Key

Teaching a vehicle immobiliser to recognise a particular 17TN can only be performed at the Lucas manufacturing site, the vehicle manufacturer's assembly site or an approved service centre. Should a vehicle security system fail to recognise a 17TN key fob, after a new battery has been fitted and re-synchronisation has been attempted, both the vehicle and the 17TN fob must be taken to an approved dealer.

Roger Lee
10/2/99