



Elliott Laboratories Inc.
www.elliottlabs.com

684 West Maude Avenue
Sunnyvale, CA 94085-3518

408-245-7800 Phone
408-245-3499 Fax

January 9, 2004

RE: Savi Technology

FCC ID: KL7-650MR-V1

In response to your comments dated December 23, 2003.

In order to show compliance to 15.209(c), please provide a measurement for both 433.92 & 1735.680 using the same measurement settings for both in order to fully show that the fundamental is higher than the harmonic. Please be sure to include information regarding the settings used. Note, it would be preferable to provide a peak measurement for both.

Additional measurements have been taken (please refer to page 9 of 20 in the test data in the Appendix of the report) using the same resolution bandwidths for both fundamental and harmonic to demonstrate compliance with 15.209(c).

2) Additionally, please confirm the QP measurement for the fundamental already provided was taken with the fundamental in a CW mode of operation, not pulsed. If pulsed, please explain compliance to 15.35(a).

All radiated measurements on the transmitter were made with the device in a CW-mode of transmission.

I hope this answers all of your questions.

Regards

A handwritten signature in blue ink that reads 'Mark Briggs'.

Mark Briggs