



Professional Testing (EMI), Inc.

1601 FM 1460, Suite B
Round Rock, Texas 78664
512/244-4371 Fax 512/244-1836

June 28, 2002

Dennis Ward
American Telecommunications Certification Body Inc.
6731 Whittier Ave.
McLean VA 22101

Re. FCC ID: KQ9903

Dennis,

This letter responds to your comments regarding an application we filed for Sercel, Inc. in May. We are awaiting responses from Sercel to several of the questions, so these will not be addressed here. Changes we could make in the original document have been incorporated, and I have attached examples of those sections of the document for your examination and comments. In the paragraphs which follow, I will address each of your comments on the application.

1. External photos do not unambiguously identify the device. New photos are being prepared by the manufacturer. We will submit them when they become available.

2. The photo of the label is not clear. A new photo is being prepared by the manufacturer. We will submit it when it becomes available.

3. No warnings for the installer regarding MPE are provided. The following paragraph will be included in the 408UL Installation Manual, in the section describing the installation and adjustment of the antennas:

"Warning: Maximum Permissible Exposure to RF energy may be exceeded if the transmitter is activated while personnel are within 1.5 meters of the antenna. Do not operate the transmitter while personnel are within 1.5 meters of the antenna."