



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 16, 2004

RE: FCC ID: KTB-HUB97_ATCB001346

Attention: Gregory M. Snyder

I have a few comments on this Application.

1. Please provide the factory tune up procedure.
2. Please note that the emissions mask plots do not provide the frequency graticules. This makes it very difficult to determine if the mask is properly overlaid. Please provide the vertical graticules for frequency on the plot. Alternately, please clearly and accurately identify the frequencies associated with each change in mask level.
3. Please note that page 30 of the report refers to 74.637(a)(3) for radiated spurious emissions. Please note that 74.637(a)(3) is for 'vestigial sideband AM video'. It appears that the actual paragraph reference should be 74.637(a)(1)(iii). Please verify and correct as needed.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.