

Report No.: 0210685
Model No.: 4009

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKR 26.438 msec

REF 107.0 dB μ V

AT 10 dB


.00 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: Cathy
(Cathy Tse)

Date: 3/8/2002

Checked By: [Signature]
(Van)

Date: 7/8

Test Result: Pass / Fail / NA

CENTER 27.120 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

Report No.: 0210685
Model No.: 4009Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

tip

MKR 26.375 msec
.00 dBREF 107.0 dB μ V


AT 10 dB

PEAK

LOG

10

dB/

VA SB
SC FC
CORRTested By: Cathy
(Cathy Tse)Date: 3/8/2002Checked By: [Signature]
(Tse)Date: 7/8Test Result: Pass / Fail / NA

CENTER 27.120 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec

Report No.: 0210685
Model No.: 4009

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

MKR 2.1250 msec

REF 107.0 dBμV

AT 10 dB

-1.02 dB


PEAK

LOG

10

dB/

VA SB
SC FC
CORR



Tested By: Cathy
(Cathy Lee)

Date: 3/8/2002

Checked By: _____
()

Date: _____

Test Result Pass / Fail / NA

CENTER 27.120 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec

Report No.: 0210685
Model No.: 4009

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

MKA 750.00 μ sec

REF 107.0 dB μ V

AT 10 dB


-.79 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By: Cathy
(Cathy Tse)

Date: 3/8/2002

Checked By: _____
()

Date: _____

Test Result: Pass / Fail / NA

CENTER 27.120 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 50.0 msec