


## RF 27MHz Mouse



1. Power by the DC battery.
2. Optical Sensor Input and Button /Z Scan Input.
3. The input signal will be sent to MCU.
4. Transfer the MCU signal to RF signal.