

SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

FCC TEST REPORT


REPORT NO. : F841510

6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

FRONT VIEW



REAR VIEW



SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F841510

SIDE VIEW



SPORTON International Inc.
TEL : 886-2-2696-2468
FAX : 886-2-2696-2255

FCC TEST REPORT

REPORT NO. : F841510

5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

FRONT VIEW



REAR VIEW

