





932908

FCC ID: L4PK5XXXCX12

Mechanical Construction



932908


FCC ID: L4PK5XXXCX12


Mechanical Construction

(Reference Modification No.2)

932908

FCC ID: L4PK5XXXCX12
Mechanical Construction
(Reference Modification No.3)






932908

FCC ID: L4PK5XXCX12


Mechanical Construction

(Reference Modification No.3)



4

932908




Intel celeron
FV524RX333
128 SL36B

FCC ID: L4PK5XXXCX12

Mechanical Construction

(Reference Modification No.4)




932908

Intel celeron
FV524RX333
128 SL36B

FCC ID: L4PK5XXCX12

Front side of main board





932908

Intel celeron
FV524RX333
128 SL36B

FCC ID: L4PK5XXXCX12

Rear side of main board



(Reference Modification No.5)



932908

FCC ID: L4PK5XXXXCX12


Mechanical Construction



932908

FCC ID: L4PK5XXXCX12

Mechanical Construction




932908

FCC ID: L4PK5XXXCX12

Mechanical Construction


932908



FCC ID: L4PK5XXXCX12

Rear side of Touch pad


932908



FCC ID: L4PK5XXXCX12


Front side of INVETER

932908



FCC ID: L4PK5XXXCX12

Rear side of INVETER



FCC ID: L4PK5XXCX12

Mechanical Construction

(Reference Modification No.6)