

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL22CW			Page 1(5)
Author Data Daoud Attayi	Dates of Test June 07-09, 2010	Report No RTS-2068-1006-65	FCC ID L6ARCL20CW	

Annex E: Test Setup Photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL22CW		Page 2(5)
Author Data Daoud Attayi	Dates of Test June 07-09, 2010	Report No RTS-2068-1006-65	FCC ID L6ARCL20CW



Figure 1 - BlackBerry® Smartphone

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL22CW		Page 3(5)
Author Data Daoud Attayi	Dates of Test June 07-09, 2010	Report No RTS-2068-1006-65	FCC ID L6ARCL20CW




Figure E2: Probe calibration and reference signal measurement setup





Figure E3: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCL22CW		Page 5(5)
Author Data Daoud Attayi	Dates of Test June 07-09, 2010	Report No RTS-2068-1006-65	FCC ID L6ARCL20CW




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup