

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW			Page 1(4)
Author Data Andrew Becker	Dates of Test March 1-2, 2012	Report No RTS-5994-1203-63	FCC ID L6AREY20CW	

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW			Page 2(4)
Author Data Andrew Becker	Dates of Test March 1-2, 2012	Report No RTS-5994-1203-63	FCC ID L6AREY20CW	



Figure E1. BlackBerry Smartphone

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW		Page 3(4)
Author Data Andrew Becker	Dates of Test March 1-2, 2012	Report No RTS-5994-1203-63	FCC ID L6AREY20CW





Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model REY21CW			Page 4(4)
Author Data Andrew Becker	Dates of Test March 1-2, 2012	Report No RTS-5994-1203-63	FCC ID L6AREY20CW	





Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup