

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFC31CW			Page 1(5)
Author Data Andrew Becker	Dates of Test March 1-23, 2012	Report No RTS-5994-1204-07	FCC ID L6ARFC30CW	

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFC31CW			Page 2(5)
Author Data Andrew Becker	Dates of Test March 1-23, 2012	Report No RTS-5994-1204-07	FCC ID L6ARFC30CW	



Figure E1. BlackBerry Smartphone

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFC31CW			Page 3(5)
Author Data Andrew Becker	Dates of Test March 1-23, 2012	Report No RTS-5994-1204-07	FCC ID L6ARFC30CW	



	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFC31CW		Page 4(5)
Author Data Andrew Becker	Dates of Test March 1-23, 2012	Report No RTS-5994-1204-07	FCC ID L6ARFC30CW




Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFC31CW			Page 5(5)
Author Data Andrew Becker	Dates of Test March 1-23, 2012	Report No RTS-5994-1204-07	FCC ID L6ARFC30CW	





Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup