Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos



This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos



This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos



This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos

This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013

Internal Photos



This report shall NOT be reproduced except in full without the written consent of RIM Testing Services
A division of Research in Motion Limited.
Copyright 2005-2013