

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFY111LW			Page 1(4)
Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1308-25	FCC ID L6ARFY110LW	

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFY111LW			Page 2(4)
Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1308-25	FCC ID L6ARFY110LW	

Telecoil (5, 18 mm)

Audio Output (0, 0)





Figure E1. BlackBerry Smartphone



	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFY111LW			Page 3(4)
Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1308-25	FCC ID L6ARFY110LW	





Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFY111LW			Page 4(4)
Author Data Daoud Attayi	Dates of Test May 31-June 06, 2013	Report No RTS-6046-1308-25	FCC ID L6ARFY110LW	




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup