

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>1(17)</b>        |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |

## APPENDIX E: PHOTOGRAPHS

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>2(17)</b>        |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |

Headset Jack

Audio Output

Voice Microphone

Figure E1. BlackBerry Smartphone

|                                                                                   |                                                                                  |                                                     |                               |                             |
|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-----------------------------------------------------|-------------------------------|-----------------------------|
|  | Document                                                                         |                                                     |                               | Page                        |
|                                                                                   | <b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                     |                               | <b>3(17)</b>                |
| Author Data<br><b>Andrew Becker</b>                                               | Dates of Test<br><b>July 02 –August 15, 2013</b>                                 | Test Report No<br><b>RTS-6046-1308-34<br/>Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E2. Body worn holster – front**

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>4(17)</b>        |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E3. Body worn holsters – back**

Author Data  
**Andrew Becker**Dates of Test  
**July 02 –August 15, 2013**Test Report No  
**RTS-6046-1308-34  
Rev 3**FCC ID:  
**L6ARFY110LW**IC  
**2503A-RFY110LW****Figure E4. Head configuration (Right Touch/Tilt)**

Author Data

**Andrew Becker**

Dates of Test

**July 02 –August 15, 2013**

Test Report No

**RTS-6046-1308-34  
Rev 3**

FCC ID:

**L6ARFY110LW**

IC

**2503A-RFY110LW****Figure E5. Head configuration (Left Touch/Tilt)**

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>7(17)</b>        |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E6. Body-worn configuration (No Holster, back side 15mm away)**

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>8(17)</b>        |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E7. Body-worn configuration (No Holster, front side 15mm away)**

Author Data

**Andrew Becker**

Dates of Test

**July 02 –August 15, 2013**

Test Report No

**RTS-6046-1308-34  
Rev 3**

FCC ID:

**L6ARFY110LW**

IC

**2503A-RFY110LW**

**Figure E8. Body-worn configuration (Vertical Holster, back facing phantom)**

|                                                                                   |                                                                                  |                                                 |                               |                             |
|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document                                                                         |                                                 |                               | Page                        |
|                                                                                   | <b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | <b>10(17)</b>               |
| Author Data<br><b>Andrew Becker</b>                                               | Dates of Test<br><b>July 02 –August 15, 2013</b>                                 | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E9. Body-worn configuration (Vertical Holster, front facing phantom)**

Author Data

**Andrew Becker**

Dates of Test

**July 02 –August 15, 2013**

Test Report No

**RTS-6046-1308-34  
Rev 3**

FCC ID:

**L6ARFY110LW**

IC

**2503A-RFY110LW**

**Figure E10. Body-worn configuration (No Holster, headset, back 10mm away)**

|                                                                                  |                                                                                  |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document                                                                         |                                                 |                               | Page                        |
|                                                                                  | <b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | <b>12(17)</b>               |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                 | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E11. Back side MHS configuration, 10 mm away**

Author Data

**Andrew Becker**

Dates of Test

**July 02 –August 15, 2013**

Test Report No

**RTS-6046-1308-34  
Rev 3**

FCC ID:

**L6ARFY110LW**

IC

**2503A-RFY110LW**

**Figure E12. Front side MHS configuration, 10 mm away**

Author Data

**Andrew Becker**

Dates of Test

**July 02 –August 15, 2013**

Test Report No

**RTS-6046-1308-34  
Rev 3**

FCC ID:

**L6ARFY110LW**

IC

**2503A-RFY110LW**


**Figure E13. Right side MHS configuration, 10 mm away**

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>15(17)</b>       |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E14. Left side MHS configuration, 10 mm away**

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>16(17)</b>       |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E15. Top side MHS configuration, 10 mm away**

|                                                                                  |                                                                                              |                                                 |                               |                             |
|----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|-------------------------------------------------|-------------------------------|-----------------------------|
|  | Document<br><b>Appendix E for the BlackBerry® Smartphone Model RFY111LW SAR Report Rev 3</b> |                                                 |                               | Page<br><b>17(17)</b>       |
| Author Data<br><b>Andrew Becker</b>                                              | Dates of Test<br><b>July 02 –August 15, 2013</b>                                             | Test Report No<br><b>RTS-6046-1308-34 Rev 3</b> | FCC ID:<br><b>L6ARFY110LW</b> | IC<br><b>2503A-RFY110LW</b> |



**Figure E16. Bottom side MHS configuration, 10 mm away**